

Свободные концы : Zorro 3

	DSL35		PPSL 160
	7850-080		TSL140
	7850-100		TSL190
	PPSL 120		TSL220
			TSL380




Схема подсоединения:

- I — A1,A2
- II — A3
- III — B1,B2,B3,St
- IV — C1,C2,C3
- K1 — клеванта
- K2 — мал. клеванта