

Harness inspection certificate

Inspection certificate number: PH_274.2019

Impact pad number: PH_274.2019

Manufacturer data

Manufacturer name: **Davinci Products Inc.**
 Representative: **Jihun Lee**
 Street: **53 sinchon-gil, Okcheon-myeon, Yangpyeong-gun**
 Post code / place: **Gyeonggi-do 12505**
 Country: **Republic of Korea**

Sample data:

Harness

Impact pad

Name:	Harmony Passenger Air	Impact pad integrated: ⁽¹⁾	Yes
Type:	ABS	Impact pad type:	Airbag
Size:	Unique	Weight of Sample[kg]: ⁽¹⁾	n/a
Weight of Sample [kg]:	3.3	Serial number: ⁽¹⁾	n/a
Serial number:	HHA-100491	Date of reception:	14.05.2019
Clip-in weight [kg]:	110		
Integrated container for rescue system:	Yes		
Volume container [cm ³]:		12000 max	
		7460 min	
Date of reception:	14.05.2019		


Test report summary

Structural test

Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	27.05.2019	14.05.2019

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **28.05.2019**
 Managing Director: **Alain Zoller**
 Signature: 

This signature approve the validity of the test reports if available; no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2)
Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651:2018**, and **EN12491:2015 chapter 5.3.2**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22